



353 Main Street  
Longmont, CO 80501 USA  
+1 720-600-7241  
info@anemoment.com

## TriSonica Sphere™ Firmware Release Notes

Publication Date: 4 August 2022

### 2.3.1 (August 2022)

- Update to bootloader to fix issue with factoryreset command corrupting the parameter memory.

### 2.3.0 (July 2022)

- Reduced the occurrence of large deviations from the data output.

### 2.2.2 (April 2022)

- Added commands to record and remove ultrasonic noise transmitted through the rings.
- Increased the length of the TriSonica ID to accommodate UUID
- Adjustments to the **diagnostic** command

### 2.1.0 (February 2022)

- Adjusted Shadow Correction Algorithm
- Added firmware build number to '**version board**' command.

### 2.0.2 (October 2021)

- Initial Release of the TriSonica Sphere Firmware

Items in **bold** indicate commands.